

Name of facility  
Address

Brooksby Melton College  
LE14 2LJ

**QUALITY RATING**

General Condition	Excellent	x	Good		Average		Poor		Very Poor	
Need for capital investment	Minimal	x	Moderate		Significant					
Facility Quality										
<i>Sports Hall 4 court</i>	Excellent	x	Good		Average		Poor		Very Poor	
<i>AGP floodlit</i>	Excellent	x	Good		Average		Poor		Very Poor	
<i>Fitness Suite</i>	Excellent		Good	x	Average		Poor		Very Poor	
<i>Grass Pitches</i>	Excellent		Good		Average	x	Poor		Very Poor	
<b>NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED</b>										4

Disability Access	Full	x	Partial		No			
Served by Public Transport	Yes*	x	No					* a short walk away
Good Natural Presence	Excellent		Good	x	Average		Poor	
Well Signposted	Good		Some	x	Poor			
Car Parking	Good	x	Some		Poor			
Development Potential	Lots	x	Some		No potential			

Key	Rating
>80%	Excellent
60% - 80%	Good
40% - 59%	Average
20%-39%	Poor
<20%	Very Poor

79%